

SPEC SHEET + MEASUREMENTS



OGIO® Force 1/4-Zip. OE341

Product photo



STAY-COOL WICKING
STRETCH
FLATLOCK SEAMS FOR COMFORT
REFLECTIVE DETAILS

- 5.2-ounce, 88/12 poly/spandex with stay-cool wicking technology
- OGIO heat transfer label for tag-free comfort
- Elastic locker loop inside neck
- Black coil zipper with locking pull and black reflective zipper garage
- Black reflective O heat transfer bar on back right shoulder
- Black reflective O heat transfer on left hem

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not use fabric softener. Do not bleach. Tumble dry low. Cool iron. Do not dry clean.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



OGIO® Force 1/4-Zip. OE341

PRODUCT MEASUREMENTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|---------------------|--------|--------|--------|--------|--------|--------|--------|--------|
| Body Length at Back | 26 1/2 | 27 1/2 | 28 1/2 | 29 1/2 | 30 1/2 | 31 1/2 | 32 | 32 1/2 |
| Chest | 17 1/2 | 19 | 20 1/2 | 22 | 23 1/2 | 25 | 27 | 29 |
| Sleeve Length | 34 1/4 | 35 | 35 3/4 | 36 1/2 | 37 1/4 | 38 | 38 3/4 | 39 1/2 |

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 32-34 | 35-37 | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 |

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SPEC SHEET + MEASUREMENTS



OGIO® Force 1/4-Zip. OE341

COLORS



Blacktop
Heather
PMS BLACK
C



Blue Indigo
Heather
PMS 2376C



Gear Grey
Heather
PMS COOL
GREY 10C